

Note:

 Set level with reference to surface
 A-A within 0.5mm bubble position
 Surface A-A ground flat to prevent 'rock'
 Operating temp : -10 to 50°C
 Survival temp : -40 to 60°C

